

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re G.O Ms 20770/PWD Dt 23-01-1970)

- 1 Name of the Officer
- 2 Name of the school
- 3 Location with name of Education District/Sub District
- 4 Classification of Building as specified in column 4 of the application for fitness certificate and size

Sindhu devi . C.S
Mary Nilayam Senior Secondary School
pangam road, Tiruvarur, Thanjavur
high school block (G-12) higher
secondary block Total Area: 4004sq

- 5 Period for which the certificate is issued
- 6 Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
- 7 Any major defects noticed which will render the building unsafe in any manner

fit

fit

- 8 Whether maintenance works have been done properly
- 9 Whether the structure is sound or not for conducting classes

Yes


Normal Weather condition Fit for conducting class.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 10/1/2025 and found to be fit / unfit to conduct classes, for the period 2025-2026 for the reasons stated above.

Place Chittoor
Date 10/1/2025



(Seal)

[Signature]
Assistant Engineer